



Sequence for Putting On

Personal Protective Equipment (PPE) for patient care that requires respirators, eye protection, gown and gloves.

For **ReadiMask** donning procedure, scan here:



1. RESPIRATOR AND EYE PROTECTION

RESPIRATOR (disposable or reusable with surgical mask) with eye protection


- Secure ear loops or ties/elastic bands at middle of head and neck
- Fit flexible band to nose bridge
- Fit snug to face and below chin
- Ensure respirator fit

-OR-
PAPR



2. LAUNDERED GOWN

- Fully cover torso from neck to knees, arms to wrists, and wrap around the back
- Fasten in back of neck and waist



3. HAND HYGIENE




-OR-



4. GLOVES

- Extend to cover wrist of isolation gown



Use Safe Work Practices to Protect Yourself and Others

- Keep hands away from face
- Limit surfaces touched
- Change gloves if torn or contaminated
- Perform hand hygiene



Scan for digital version of poster